



TS 4 x 4 x 1/2  
WPL 7 x 3/4 x 1'-3  
W 1 1/8 Ø HO'S



W14 x 53  
WPL 11 x 1 1/2 x 1'-3  
W 1 1/8 Ø HO'S




W14 x 68  
WPL 11 x 1 1/2 x 1'-3  
W 1 1/8 Ø HO'S


TOP OF CONC. PEDESTAL @  
FIN. FLR. = 100'-0

FIN. FLR. = 100'-0  
I.O. PEDESTAL


FIN. FLR. = 100'-0  
I.O. PEDESTAL



3/4 Ø ROD x1'-0  
W 3-3/4 Ø NUT & 2-3/4 Ø WASHER



3/4 Ø ROD x1'-0  
W 3-3/4 Ø NUT & 2-3/4 Ø WASHER





3/4 Ø ROD x1'-0  
W 3-3/4 Ø NUT & 2-3/4 Ø WASHER


**DETAIL #1**  
(8)

**DETAIL #2**  
(8)

**DETAIL #3**  
(8)



W14 x 43  
WPL 11 x 1 1/2 x 1'-3  
W 1 1/8 Ø HO'S




W8 x 28  
WPL 10 x 1 x 1'-2  
W 1 1/8 Ø HO'S


FIN. FLR. = 100'-0

TOP OF CONC. PEDESTAL  
EL. = 100'-0

I.O. PEDESTAL



3/4 Ø ROD x1'-0  
W 3-3/4 Ø NUT & 2-3/4 Ø WASHER



1 Ø ROD x1'-7  
W 3-1 Ø NUT & 2-1 Ø WASHER

**DETAIL #4**  
(8)

**DETAIL #5**  
(4)

PROJECT:	A NEW FACILITY FOR FIRST COMMUNITY BANCSHARES, INC. SEARCHY, ARKANSAS
ARCH:	ROARK, PARKINS, PERRY, YELVINGTON
CONTRACTOR	
SCALE:	1/2" = 1'-0"
JOB #	

**SHT. AB2**